

Task Title: Automotive Vehicle Inspection

OALCF Cover Sheet – Learner Copy

Learner Name:		
Date Started:		
Date Completed:		
Successful Completion:	Yes No	
Goal Path:	Employment	Apprenticeship
Secondary School	Post Secondary	Independence

Task Description: Use an automotive vehicle inspection document to record a vehicle's current condition.

Main Competency/Task Group/Level Indicators:

- Find and Use Information/Interpret documents/A2.2
- Communicate Ideas and Information/Complete and create documents/B3.1a
- Communicate Ideas and Information/Complete and create documents/B3.2a

Materials Required:

• Pen/pencil and paper and/or digital device

Learner Information

When customers bring their car into a garage, Automotive Service Technicians do a routine inspection. They will look at many parts of the car, including the windshield, lights, engine, underside of the car, fluid levels, brakes and tires.

While they do this inspection, Automotive Service Technicians and apprentices fill out inspection reports to document what they see. These inspection reports may indicate recommended maintenance or repairs to the vehicle.

Scan the "Vehicle Report Card".

Task Title: AutomotiveVehicleInspection_A_A2.2_B3.1a_B3.2a

Work Sheet

Task 1: An automotive service technician is inspecting a white 2019 Ford Taurus with an odometer reading of 238,126 km. Enter the odometer reading into the appropriate boxes on the vehicle report card.

Answer: No written response required here.
Task completed: Yes:
Task 2: When doing a visual parameter inspection, the automotive service technician notices that the right front (RF) headlight is burnt out. It needs to be replaced immediately. Record this information on the vehicle report card.
Answer: No written response required here.
Task completed: Yes:
Task 3: The tread on the right front (RF), left front (LF), right rear (RR) and left rear (LR) tire measures 2/32, which is the minimum legal tread depth. At this level, tires are considered bald and unsafe. Record the tire tread depth on the vehicle report card, and indicate that these four tires need immediate attention.
Answer: No written response required here.
Task completed: Yes:
Task 4: The car's owner mentions that the check oil light is on. When the automotive service technician looks under the vehicle, they see that oil is leaking. They check the fluid levels and find the oil is very low and needs to be replaced immediately. Check the appropriate boxes on the vehicle report card.
Answer: No written response required here.
Task completed: Yes:

Vehicle Report Card

